SERVICE BULLETIN

WM

MW

LG Electronics Inc.

Date of issue: 28 May. 2007

Buyer Model: LDS5811,LDF7811,LDF7810,LDF6810,LDF8812

LGE Model: LD-6090,LD-6100,LD-6105,LD-6300,LD-6310

Applicable Serial No: 703KWXXXXX ~

Subject: BLDC Motor Magnet Crack

1.Phenomenon: LE Error or Motor shaft locked (Won't Turn)

2.Reason: BLDC Motor Magnet is cracking. It was caused by

chemical attack of the oils used in the manufacturing of the motor.

3.Improvement

- Sump Assembly



P/No:AJH31248602(New) 3485ED1002B(Old)

There are two Sump Assemblies Energy consumption & wash performance was improved Jan. 2007. (Refer to the SVC Bulletin No. IDSW20070074)

- BLDC Motor





Rotor Assy

P/No:4681ED1004A

15 March 2007~

- -Core Press Oil improvement
- -Injection Method Optimization

	*		Alphabetic Code	Numeral Code						
	nterch	Α	Interchangeable : Old and new parts can be used in products as the bulletin regardless of manufacturing date.	1	To improve performance					
	Interchangeability	В	Old parts can be substituted for new parts :Old parts can be used in products regardless of manufacture date. New parts can be used in new products only.	3 4	To improve productivity To improve reliability Change of material or					
	oility (С	New parts can be substituted for old parts: Only new parts can be used in products regardless of manufacture date.	5	dimension Addition					
	Cod	ח	Not interchangeable : New parts can be used in new products	6	Deletion					

Y.H.KIM

Y.H KIM

Dish Washer Engineering Design Department.

SERVICE BULLETIN






LG Electronics Inc.

Date of issue: 28 May. 2007

4.SVC Method


Improved parts have been applied to all models that were produced since 15 March 2007. Use the following diagnostic chart to determine if the motor needs to be replaced.



When replacing the BLDC motor (P/n 4681ED1004A) in the dishwasher, verify the motor manufacturing date as shown below. Improved BLDC motor began 15 March 2007. (Verify date on motor – the part number has not been changed)

If manufacturing date is before 15 March 2007 DO NOT USE THE MOTOR.

Manufactured date is marked on the bottom of upper bracket.



[Differences before and after]

[P/No] Motor ASM : 4681ED1004A

The date code is the only visible difference between parts. The part number is unchanged.

[Parts Stock]

All old stock (dated prior to 15 Mar 2007) must be scrapped. All old motors will be replaced with new stock.

Appendix

Information of Sump Assy P/No. & PCB P/No.

(Refer to the SVC Bulletin No. IDSW20070074)

-Some parts have been changed to enhance energy performance (Sump, PCB, Blower, Vent, Water Guide)

(Energy consumption for one year reduced from 350kWh/year to 294kWh/year)

Main PCB Assembly								
Period	501 ~ 512	601	602 ~612	701~				
Spec	-	Add relay in Base* (Except LDF6810)	Change IPM maker & Add thermistor	Change PGM & Housing (Energy factor upgrade)				
LDF7811- -	6871DD1006A	6871DD1014A	6871DD1006E	6871DD1006J				
LDF7810- -	6871DD1006C	6871DD1014C	6871DD1006G	6871DD1006L				
LDS5811- -	6871DD1006B	6871DD1014B	6871DD1006F	6871DD1006K				
LDF6810- -	-	6871DD1006D	6871DD1006H	6871DD1006M				

Interchangeable Parts: 6871DD1006A & 6871DD1006E; 6871DD1006C & 6871DD1006G; 6871DD1006B & 6871DD1006F; 6871DD1006D & 6871DD1006H

Sump Assembly							
Period	501 ~ 512	601 ~612	701~				
P/No	3485ED1002A	3485ED1002B	AJH31248602				
Shape		The state of the s					

P/No: 3485ED1002A & 3485ED1002B are interchangeable.

New models with updated parts can be identified by ECN code on Rating label and confirmed by lower nozzle. (Applied date: 02.Jan.2007)
Old parts *cannot* be used in the new models.

*See SB IDSW20060052 Heater Relay

